



Saddlebrooke Villas

Weekly Service Report

Attn: Fran Meckler

For the week of:

6/24/24

Services performed the previous week of: 6/17/2024

Policing/debris removal: checking property for debris and damage.

Irrigation Management: Lot 50 on Haven Ln - Leak repaired
Lot 41 on casual Dr - Leak repaired

Rotation Detail: Spray Tech was on site last week spraying throughtout with the Spray Rig
General Plant rejuvenation and cutback
Blowing out heavy leaf debris accumualtion

Other:

Services scheduled for the week of: 6/24/24

Monday

Policing/debris removal: Police for trash and debris.

Irrigation Management: Turn on Drip Valves to run the system and check for any new leaks in areas worked in

Weed Control: Crew will continue Spot Spray weeds throughout property

Rotation Detail: Service Lots 5 - 10 along Casual Drive

Other: General Plant rejuvenation and cutback
Blowing out heavy leaf debris accumualtion

Tuesday 6/25/24

Policing/debris removal: Police for trash and debris.

Irrigation Management: Turn on Drip Valves to run the system and check for any new leaks in areas worked in

Weed Control: Crew will continue Spot Spray weeds throughout property

Rotation Detail: Service Lots 11- 16 along Casual Drive

Other: General Plant rejuvenation and cutback
Blowing out heavy leaf debris accumualtion

Wednesday 6/26/24

Policing/debris removal: Police for trash and debris.

Irrigation Management: Turn on Drip Valves to run the system and check for any new leaks in areas worked in

Weed Control: Crew will continue Spot Spray weeds throughout property

Rotation Detail: Service Lots 17 - 22 along Casual Drive

Other: General Plant rejuvenation and cutback
Blowing out heavy leaf debris accumualtion



Thursday

6/27/24

Policing/debris removal: Police for trash and debris.

Irrigation Management: Turn on Drip Valves to run the system and check for any new leaks in areas worked in

Weed Control: Crew will continue Spot Spray weeds throughout property

Rotation Detail: Service Lots 74 - 79 along Carefree Drive and Holiday Drive

Other: General Plant rejuvenation and cutback
Blowing out heavy leaf debris accumualtion

Friday

6/28/24

Policing/debris removal: Police for trash and debris.

Irrigation Management: Turn on Drip Valves to run the system and check for any new leaks in areas worked in

Weed Control: Crew will continue Spot Spray weeds throughout property

Rotation Detail: Service Lots 73 - 68 along Carefree Drive

Other: General Plant rejuvenation and cutback
Blowing out heavy leaf debris accumualtion

General Information:

Workorder requests will be assessed and addressed accordingly as they come in and followed up with a Completion email for record

Irrigation Controllers and Valves will continued to be checked and tested throughout the week to check for new leaks and proper function

Pending Tasks:

Pending Irrigation Concerns:

Irrigation Tech scheduled to investigate the following concerns:


Proposal to replace Drip Valves - check condition of each Valve and Irrigation Timer

Glenn Brchan
President

Platification boundaries, footprints

- Plot area of lot 99A
- Side Yard Lot 20A
- Side Yard Lot 20B
- Side Yard Lot 20C
- Side Yard Lot 20D
- Side Yard Lot 20E
- Side Yard Lot 20F
- Side Yard Lot 20G
- Side Yard Lot 20H
- Side Yard Lot 20I
- Side Yard Lot 20J
- Side Yard Lot 20K
- Side Yard Lot 20L
- Side Yard Lot 20M
- Side Yard Lot 20N
- Side Yard Lot 20O
- Side Yard Lot 20P
- Side Yard Lot 20Q
- Side Yard Lot 20R
- Side Yard Lot 20S
- Side Yard Lot 20T
- Side Yard Lot 20U
- Side Yard Lot 20V
- Side Yard Lot 20W
- Side Yard Lot 20X
- Side Yard Lot 20Y
- Side Yard Lot 20Z

6-24 100A
 6-25 100B
 6-26 100C
 6-27 100D
 6-28 100E



Site Plan
 Scale 1:50
 GRAPHIC SCALE

NEW PURES SYSTEMS
 V - VILLAS